




# SK7-BL

## Instruction Manual

















|  |              |                        |              |                       |              |              |              |             |
|--|--------------|------------------------|--------------|-----------------------|--------------|--------------|--------------|-------------|
| 1<br>1X<br>                                | 2<br>2X<br>  | 3<br>2X<br>M4x35<br>   | 4<br>1X<br>  | 5<br>1X<br>           | 6<br>1X<br>  | 7<br>1X<br>  | 8<br>1X<br>  | 9<br>1X<br> |
| 10<br>1X<br>                               | 11<br>1X<br> | 12<br>6X<br>ST4X40<br> | 13<br>6X<br> | 14<br>8X<br>M4x16<br> | 15<br>1X<br> | 16<br>1X<br> | 17<br>1X<br> |             |
| 18<br>1X<br>5mm<br>4mm<br>3mm<br>2.5mm<br> |              |                        |              |                       |              |              |              |             |






1






2






3





4



5



6



7

